

Note: S8 Multiple places throughout line.

## Rehabilitation Work Items Engineered to 30% CW Subdivision - Cheney to Coulee City MP 1.2 to 108.6

**Bridge Rehab Items** 

			Prevent Service Disruption Anticipated	Prevent Service Disruption Anticipated	Avoid Further
			Within Two	Within Five	Deterioration
Item	Location	Potential Project Items	Years	Years	For Five Years
B1	Br 1.38 Repairs				
		Surface Dumps		\$7,000	
<b>B2</b>	Br 11.90 Repairs				
		Replace Bridge Tie	\$7,500		
		Replace Subcap		\$3,500	
		Surface Dumps	\$7,000		
		Shim Pile		\$600	
В3	Br 12.10 Repairs				
		<b>Surface Dumps</b>	\$7,000		
		Replace Subcap		\$3,500	
<b>B4</b>	Br 13.70 Repairs				
		Surface Dumps	\$7,000		
		Replace Bridge Cap		\$3,500	
B5	Br 30.14 Repairs				

		Surface Dumps	\$3,500		
<b>B6</b>	Br 57.10 Repairs				
		Surface Dumps		\$7,000	
<b>B7</b>	Br 67.80 Repairs				
		Surface Dumps		\$7,000	
B8	Br 68.30 Repairs				
		Surface Dumps		\$7,000	
		Shim Pile		\$3,000	
В9	Br 69.90 Repairs				
		Surface Dumps		\$7,000	
	-				
B10	Br 70.60 Repairs				
		Surface Dumps		\$7,000	
B11	Br 72.20 Repairs				
		Replace Subcap		\$3,500	
		Surface Dumps		\$7,000	
B12	Br 73.20 Repairs				
		Surface Dumps		\$7,000	
W 10	D = ( (0 D				
B13	Br 76.60 Repairs	D. J. D. J. GW		<b>da</b> 222	
		Replace Bridge Sill		\$3,000	
D44	D 07 00 D	Surface Dumps		\$7,000	
B14	Br 85.00 Repairs	C & D		Φ# 000	
		Surface Dumps		\$7,000	
D45	D 07 70 D				
B15	Br 85.50 Repairs	DI Di		ф2 <b>с</b> оо	
		Place Riprap		\$3,600	

		Headwall		\$12,000	
		<b>Surface Dumps</b>		\$7,000	
B16	Br 87.90 Repairs				
		Surface Dumps		\$7,000	
B17	Br 94.40 Repairs				
		Walkways	\$2,500		
		Replace Bridge Handrails (All)	\$500		
		Mud Block	\$8,000		
		Replace Bridge Cap	\$3,500		
B18	Br 94.70 Repairs				
		Shim Bent		\$1,200	
		Surface Dumps		\$7,000	
B19	Br 95.10 Repairs				
		Surface Dumps		\$7,000	
				-	
B19	Br 98.60 Repairs				
		Surface Dumps	\$7,000		
		Replace Bridge Cap		\$7,000	
Draina	age / Ditching Items				
D1	MP 26 - 27Area Ditching				\$36,960
D2	MP 37 - 38 Area Ditching				\$48,048
D3	MP 44 - 45 Area Ditching				\$27,720
D4	MP 53 - 54 Area Ditching				\$27,720
D5	MP 56 - 57 Area Ditching				\$27,720

İ	1	1	1	I	1
<b>D6</b>	MP 71 Area Ditching				\$18,480
<b>D7</b>	MP 80 - 81 Area Ditching				\$18,480
D8	MP 89 -90 Area Ditching				\$18,480
_					, , , , ,
D9	MP 91 - 92 Area Ditching				\$18,480
					,
D10	MP 94 - 95 Area Ditching				\$27,720
D11	MP 98 - 100 Area Ditching				\$27,720

Spot and Track Repairs					
S1	MP 1 to 2 Repairs		\$22,170		
		Furnish & Install Cross Ties			
		Surface Line and Dress Track			
S2	MP 2 to 3.6 Repairs		\$56,368		
		Furnish & Install Cross Ties			
		Perform Minor Joint Rehab			
		Surface Line and Dress Track			
		Furnish & Unload Ballast			
S3	MP 13.5 -15.8 Repairs		\$56,879		
50	in the tens repairs	Furnish & Install Cross Ties	Ψ20,012		
		Perform Minor Joint Rehab			
		Surface Line and Dress Track			
S4	MP 36-37 Repairs		\$24,730		
34	Wir 50-57 Repairs	Furnish & Install Cross Ties	φ24,730		

		D. C M T. A.D.L.L			
		Perform Minor Joint Rehab			
		<b>Surface Line and Dress Track</b>			
<b>S5</b>	MP 63 -65 Repairs			\$71,960	
		Furnish & Install Cross Ties			
		Perform Minor Joint Rehab			
		<b>Surface Line and Dress Track</b>			
		Furnish & Unload Ballast			
<b>S6</b>	MP 96 -97 Repairs			\$50,230	
		Furnish & Install Cross Ties			
		Perform Minor Joint Rehab			
		<b>Surface Line and Dress Track</b>			
		Furnish & Unload Ballast			
S7	MP 106 -107.5 Repairs			\$41,385	
		Furnish & Install Cross Ties			
		Perform Minor Spot Joint			
		Rehab			
S8	Other General Spot Repairs				
		Thermal Adjustment and Surface	e	\$171,510	
		Furnish & Install Cross Ties @ (	Clusters		
		Perform Minor Spot Joint			
		Rehab			
		Spot Surface Line and Dress Track Furnish & Unload Ballast			
		Furnish and Install Switch Ties			
		Surface Turnout			